NO. 111

Dated: 10/06/2025

It is certified that the existing building	THE STATE OF THE S	(name of the building or premises) at Rurka
Road ,Madevi Teh. And District Malerkotla	(address) is having (s)flo	oor (s) as per details below:

In school	Block	Block (2)	Block (3)
No. of floor (s)in the Block	3	NA .	NA NA

The building is owned/occupied by The Oasis School, Rurka Road, Madevi Teh. And District Malerkotla (name of the institution) have complied with the Building Safety Requirements and verified by the officers concerned of Executive Engineer PWD(Name of Department/Govt.) on 05-06-2025 (date of inspection) in the presence of Mohammad Salim Chairman (name and address of the Manager/Secretary or his representative) and that the Building/Premises is fit for occupancy for running school with effect from 01-04-2085 for a period of one year 31-03-2086 in accordance with rule and subject to compliance of the specific condition as appended.

- Fire Safety certificate, electrical certificate should be obtained separately from the concerned department.
- 2. Keeping the safety of the school building as a priority, it is the responsibility of the school management to repair the building. Despite this report, the school management is responsible for the security of the building in all respects.
- 3. The school must provide staff members with appropriate safety training, including procedures for handling emergency first aid and evacuation protocols.
- 4. If the walls, foundations and roofs of the building collapse due to natural calamity or any other reason, then the school should immediately inform this office about the condition of the building and the building should be put into use only after conducting an inspection.
- 5. The school should have a plan to deal with the untoward incident, including the safe evacuation of children from the building during an emergency and a plan to coordinate with the concerned department. The school should regularly review and update this plan to ensure its effectiveness.
- 6. If any addition, alternation, expansion and modification is required or to be done by the school in this building, then an immediate inspection should be arranged by this office and it is safety certificate should not be obtained from this office again after completion of that part.
- The Johnaid Singh; Mehten & Associated has been approved and according to their certificate the school is safe for the session 2025-26, but this school is not constructed by this department so the safety of the school structure especially from earthquake point of view cannot be ensured by this department.
- 8. According to the covered area if the school, <u>Challun No -(PAFFGSEP</u> side ten thousand rupees (10,000) received as a building inspection fee. The school management will be responsible for renewing the fire safety certificate within the time limit.

Issued on 10/06/2025 at PWD office Malerkotla by Executive Engineer

Strike out whichever is not applicable. In case of block is more than six use separate sheet for details.

Signature with Seal:

Name: Sub Divisional Engineer

Provi. Sub Division B&R

MALERKOTLA

Name and Address of Department/office:

Chairman The Oasis School Madevi, Malerkotla

